

Illinois Commerce Commission
Pipeline Safety
Field Trip Report

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Mike Kershaw	Total Man Days: 4
Pipeline Safety Representative(s): Jim Watts, Valerie Schwing	
Company Representative to Receive Report: Michael Fuller	<u>Emailed Date:</u>
Company Representative's Email Address: mfuller2@ameren.com	11/14/2013

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Record Audit	Hookdale	Jim Watts, Valerie Schwing	Hookdale Storage	2	9/25/2013	Chuck Tebbe, George Baron, Mike Kershaw
Standard Inspection - Field Audit	Hookdale	Jim Watts, Valerie Schwing	Hookdale Storage	2	9/26/2013	

Statement of Activities

On September 25-26, 2013, Staff conducted a record and field audit of the Ameren Illinois Hookdale Aquifer Storage and Compressor Station. The field audit included a walk through of the compressor station and inspections of well sites located in the storage field. During the field audit Staff performed visual pipe inspections on above ground piping looking for indications of atmospheric corrosion and observed no indications of corrosion present, inspected the blow down stack locations, completed a walk through of the compressor building, performed pipe to soil potential testing and reviewed the placement of line markers at the road crossing and well sites inspected. The audits were performed to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. The record audit included a review of company documents regarding the specific code sections as identified on the attached inspection form(s).

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

NO NOPVs CORRECTED.